

When the Underbin Conveyor is not used for long periods of time, the following procedure must be followed to reduce the chance of rust, corrosion and fatigue of the conveyor.



A dust mask and protective rubber gloves shall be used when cleaning the machine.

- 1. Thoroughly wash the entire machine to remove all dirt, mud, debris or residue.
- 2. Inspect all moving or rotating parts to see if anything has become entangled in them. Remove the entangled material.
- 3. Lubricate all grease fittings. Make sure that all grease cavities have been filled with grease to remove any water residue from the washing. This also protects the bearing seals.
- 4. Remove drive assembly cover. Clean entire area and ensure drive belt and chain are clean and free of debris. Lubricate drive chain.
- 5. Touch up all paint nicks and scratches to prevent rusting.
- 6. Cover the electric motor with a water proof tarpaulin and tie securely in place.
- 7. Do not allow children to play on or around the machine.